



June 11, 2010


Product Quality Advisory

Subject: Potential Quality Concern – SA29 Hard Hat

Salisbury Engineering and Quality Assurance have identified a potential quality issue with a hard hat (part# SA29) affecting the AS1000HAT and Salisbury Pro-Hoods which include part numbers: FH8BL, FH11BL, FH20BL, FH31RB, FH40GY, FH40GYLT, FH55GY, FH75GY, FH100TW.

It has come to our attention that the SA29 hard hats we are providing for the above part numbers may have a slightly enlarged slot on the right side of the hard hat which may cause the clip on one side of the face shield to not securely fit in place. This may cause the clips to pull out which can cause an inconvenience to the user. Our findings indicate that these affected hard hats have a manufacturing date of November, 2009, through May of 2010. Please be aware that this problem has been corrected for all orders moving forward.

Please see pictures that more clearly explain the issue:



Hard hats with the above manufacturing dates may be returned to Salisbury by Honeywell for a free replacement which will rectify the problem. Please call your local Lineman's Testing Laboratories sales representative to begin process for replacement. Thank you for your co-operation.

www.ltlutilitysupply.com